


ENGR480 MANUFACTURING SYSTEMS

Spring 2012





ENGR480 MANUFACTURING SYSTEMS

- MWF 10:00, Lab Tue 2:00
- Read Syllabus for other info



OUR MANUFACTURING COMPANY

FLASHOFGENIUS INC



LATHE COORDINATE SYSTEM

MORI SEIKI
THE MACHINE TOOL COMPANY

COORDINATES


2. X-Axis and Z-Axis

Basic model of NC lathe has two numerically controlled axes, called X-axis and Z-axis.

X-axis The axis along which the cross slide moves.


Z-axis The axis along which the carriage moves.

The direction of an axis is determined by the positive (plus) and negative (minus) signs.




WORKPIECE ZERO POINT


- Coordinate system zero point is
 - centerline of spindle (X)
 - with normal spindle rotation, machining is in +X
 - back face of part
 - +Z is machining part
- X dimensions are *diameter*, not radius



WORKPIECE ZERO POINT




WORKPIECE ZERO POINT




4. Tool Command Point


a) O.D./Face Turning



b) O.D. Grooving




c) O.D. Threading



d) I.D. Turning




e) I.D. Grooving



Example

Let's find out the dimensional data (actually, coordinate values) of five points (① to ⑤) in the drawing below.




Z=0 (Fig. 1-6)

- 0 _____
- ① X_____ Z_____
- ② X_____ Z_____
- ③ X_____ Z_____
- ④ X_____ Z_____
- ⑤ X_____ Z_____

M30

ABSOLUTE PROGRAMMING


- Point 1: X40.0 Z90.0
- Point 2: X50.0 Z85.0
- Point 3: X50.0 Z40.0
- Point 4: X80.0 Z40.0
- Point 5: X100.0 Z30.0



INCREMENTAL PROGRAMMING

- In incremental programming, only the change in X and Z are given. Change in X is U, change in Z is W.
- ONLY USE FOR MOVING AWAY FROM PART, NOT CUTTING!
- Point 1: X40.0 Z90.0
- Point 2: U10.0 W-5.0
- Point 3: W-45.0
- Point 4: U30.0
- Point 5: U20.0 W-10.0

7. Cutting Conditions



7.1 How to Determine Cutting Conditions

- (1) Cutting speed (spindle speed) : Material and shape of workpiece
Insert material (hardness in high temperature and wear resistivity)
- (2) Cutting feedrate : Rigidity of the machine and tools
Nose radius of insert ($F_{max} \leq Nr/2$)
Chip breaker shape
Surface finish specified in the drawing → Nose radius
- (3) Depth of cut : Rigidity of the machine and tools
Main motor output
Insert thickness ($D_{max} \leq$ Insert thickness)
Cutting edge length of insert
Chip breaker shape
- (4) Workpiece holding conditions : Workpiece holding status and method
Workpiece shape
Size and balance of jaws
Chucking pressure
Tailstock spindle thrust force

Major Five Functions That Control NC Lathe

1. **G Function: Preparatory function**

Commands related to X-/Z-axis feed control/G00, G01, G02

2. **M Function: Miscellaneous function**

ON/OFF commands output from the CNC to the NC lathe/M00, M03, M08

3. **T Function: Tool selection function**

Calling the tool to be used/T0101 (4-digit T code)

4. **S Function: Spindle speed (min^{-1}) and cutting speed (m/min)**

Spindle speed command/S500 (= 500 min^{-1})

Cutting speed command/S200 (= 200 m/min)

5. **F Function: Feedrate command (mm/rev)**

Tool feedrate command/F0.3 (= 0.3 mm/rev)

BASIC PATTERNS OF PROGRAM (1)

O1
N1
G50S2000
G00T0101
G962S00M03




G00U1.0Z10.0
X300.0Z150.0
M01
M30;

Program number (O1~O9999)

Program name

Must be specified at the beginning of all programs.

In the storage area



NC reset & rewind

BASIC PATTERNS OF PROGRAM (2)

O1
N1
G50S2000
G00T0101
G96S200M03

⋮

G00U1.0Z10.0
X300.0Z150.0
M01
;

Sequence number (to be specified at the beginning of a part program)

Usually, a sequence number is specified at the beginning of individual machining processes to identify the processes.

- Rough O.D. turning N1
- Rough I.D. turning N2
- Finish O.D. turning N3
- N4
- N5
- Thread cutting N6



BASIC PATTERNS OF PROGRAM (3)

O1
N1
G50 S2000

G00 T0101

G96S200M03

.....

G00U1.0Z10.0

X300.0Z150.0

M01

;

The command specifying
the allowable maximum
spindle speed



BASIC PATTERNS OF PROGRAM (4)

```
O1  
N1  
G50S2000  
G00 T0101  
G96S200M03  
.....  
  
G00U1.0Z10.0  
X300.0Z150.0  
M01
```

The command
specifying the tool
number and the tool
position offset number



BASIC PATTERNS OF PROGRAM (5)

O1

N1

G50S2000

G00T0101

G96

S200M03

The command specifying the cutting speed, spindle rotation in the normal direction and spindle revolving speed

G00U1.0Z10.0

X300.0Z150.0

M01



BASIC PATTERNS OF PROGRAM (6)

```
O1  
N1  
G50S2000  
G00T0101  
G96S200M03  
.....  
G00U1.0Z10.0  
X300.0Z150.0  
M01  
;
```

Moving the tool away
from the workpiece after
finishing the machining



BASIC PATTERNS OF PROGRAM (7)

O1

N1

G50S2000

G00T0101

G96S200M03




G00U1.0Z10.0

X300.0Z150.0

M01

;



Moving the tool to the
position where turret
rotation is possible
Optional stop



THE LAST BLOCK

$\bar{O}1$
N1
G50S2000
G00T0101
G96S200M03
⋮
G00U1.0Z10.0
X300.0Z150.0
M01
⋮
M30

← NC reset and rewind



THANK YOU for your careful
attention to my lecture.


This ends the explanation of
programming.

*I hope all of
you enjoyed
to understand
programming
basics.*



LATHE TOOLING

- Turning
- Boring
- OD Grooving
- ID Grooving
- Face Grooving
- OD Threading
- ID Threading



Cutting process Cutting procedure	1	2	3
	End face cutting	Outer diameter cutting	Grooving
1. Cutting method : Rough Semi Finish			
2. Cutting tools			
3. Cutting conditions : Feedrate Cutting depth			
4. Tool path			

CNC LATHE PROGRAMMING

1 block



Sequence number

Preparatory function


Dimension word

Miscellaneous function

Spindle function

Tool function

End of block



G-CODES FOR TURNING

G00	Rapid positioning
G01	Linear interpolation (feeding)
G02	CW Circular interpolation
G03	CCW Circular interpolation
G04	Dwell
G20	Inch system
G21	Metric system
G28	Return to reference point
G50	Limit spindle speed

G-CODES FOR TURNING


G54	Select work coord system #1
G70	Finishing cycle
G71	Roughing cycle
G72	Facing cycle
G76	Threading cycle
G96	Constant surface speed mode
G97	Constant spindle speed mode
G98	Feed per minute mode
G99	Feed per revolution mode

M-CODES FOR TURNING


M00	Program Stop
M01	Opt. Program Stop (panel controlled)
M03	Start spindle (normal rotation)
M04	Start spindle (reverse rotation)
M05	Stop spindle
M08	Start coolant
M09	Stop coolant
M10	Close chuck
M11	Open chuck
M30	Program end

EXAMPLE PROGRAM

```
%  
O1 (THAT'S AN OH NOT A ZERO)  
; (EXAMPLE PROG - TURN PLUG 20.0MM OD X 17MM LONG)  
; (STOCK: ALUM 1.5" X 17MM + 10MM)  
;  
; (T1- CNMG 55DEG DIAMOND)  
; (T2- VNMG 15DEG DIAMOND)  
; (T10- 3.175MM CUTOFF)  
;  
; (VARIABLES)  
#500=38.1 (STOCK DIAMETER)  
#501=17.0 (STOCK LENGTH)  
#502=75.0 (SURFACE M/MIN FOR CUTTING ALUM)  
#503=0.4 (ROUGHING FEED: MM/REV)  
;  
N1  
G54 (WORK OFFSET)  
G21 (METRIC)  
G28 U0 W0 (GO HOME)  
G50 S2000 (MAX SPINDLE SPEED)
```




```
;
; (FACE WITH 55DEG DIAMOND TOOL AND SPEED LIMITING)
;
G00 T0101          (CUTOFF TOOL)
G50 S1000         (CLAMP SPEED AT 1000RPM)
G96 S#502         (CONST SURF SPEED)
G99              (FEED PER REV)
;
M03              (SPINDLE ON, NORMAL DIR)
G00 Z#501        (INITIAL Z POSITION)
G00 X[#500+1.0]  (INITIAL X POSITION)
M08             (TURN ON COOLANT)
G01 X-0.1 F#503  (FACE FROM OUTSIDE DOWN TO -0.1MM)
G01 Z[#501+1.0] F1.0 (MOVE OFF FROM FACE)
M09             (TURN OFF COOLANT)
M05             (TURN OFF SPINDLE)
G28 U0 W0       (RETURN TO HOME)
M01             (OPTIONAL STOP)
```




```
;
; (ROUGH OD 38.0 TO 20.5MM)
; (USE 2.0MM DOC -> 8 PASSES)
;
N2
G00 T0101          (55DEG DIAMOND TOOL, TOOL 1)
G50 S2000          (CLAMP SPEED AT 2000)
G96 S#502          (CONST SURF SPEED)
G99                (FEED PER REV)
G00 X[#500 + 0.5] Z#501  (INITIAL POINT FOR ROUGHING)
M03                (SPINDLE ON)
M08                (TURN ON COOLANT)
G00 X36.0 Z#501
G01 X36.0 Z5.5 F#503 (FIRST PASS)
G01 X[#500+0.5] F#503 (RETRACT X)
G00 Z#501          (RETRACT Z)
G00 X34.0
G01 X34.0 Z5.5 F#503 (SECOND PASS)
G01 X[#500+0.5] F#503
G00 Z#501
G00 X32.0
G01 X32.0 Z5.5 F#503 (THIRD PASS)
G01 X[#500+0.5] F#503
...
```

```
;
; (FINISH OD 20.0MM)
;
N3
G00 T0202 (VNMG 15DEG DIAMOND)
G00 X19.0 (POSITION FOR START OF
CHAMFER)
G00 Z[#501+0.5]
G01 X20.0 Z[#501-0.5] F0.1 (CHAMFER 0.5MM)
G01 Z0.0 F0.1 (FINISH TURN)
G01 X[#500+0.5] F0.1 (BACK OFF)
M09
M05
G28 U0 W0 (GO HOME)
M01
```




```
;
; (CUTOFF)
G00 T1010
G00 Z-3.175          (CUTOFF BLADE IS 3.175MM WIDE)
G00 X[#500+2.0]
M03
M08
G50 S1000           (CLAMP SPEED AT 1000RPM)
G96 S#502           (CSS)
G01 X-0.1 F0.05     (CUTOFF)
G01 X[#500+2.0] F4.0 (RETRACT)
M09
M05
G28 U0 W0
M30                 (END PROGRAM)
%
```



ASSIGNMENT FOR LAB

