



MATERIAL REMOVAL

- Turning
 - work rotates, chip forming
- Milling
 - tool rotates, chip forming
- Grinding
 - tool rotates, work may rotate too, no chips




CHIP FORMATION




- Cutting rate \rightarrow dist/time ($\text{RPM} \times \text{cutter diam} \times \pi$)
- Feed rate \rightarrow dist/time (rate of work motion \times # teeth)

TURNING















- Lathe
- Turning Center





LATHE



LATHE




TURNING CENTER




MILLING

- Vertical Mill
- Horizontal Mill
- Horizontal Machining Center



MILLING - HORIZONTAL MACH CENTER



E955

MILLING - 5 AXIS MACHINING CENTER




V5-2000




MILLING

- CNC programming
- Clamping and fixturing




CNC PROGRAMMING




G00Z0.1	Linear translation, raise bit to 0.1"
X1.Y1.382	Linear tran, to 1" in X, 1.382" in Y
G01Z-0.75F10	Linear feed, -.75" in Z, Feed rate "10"
G03X1.382Y1.I0.382J0.F20	CCW Arc, Start pnt, radius, arc len
G01X3.618	Linear feed, same feed rate
G03X4.Y1.382I0.J0.382	CCW Arc
G01Y2.4589	Linear feed
X1.382	
G03X1.Y2.618I0.J-0.382	CCW Arc
G01Y1.382	Linear feed
G00Z0.1	Linear translation (raise bit)
X0.1511Y3.5	Linear translation (move to new
G01Z-0.75F10	Linear feed to -0.75" depth
...	...
M30	End of data

JIGS AND FIXTURES


- Setup time is non-productive time
- Money is only being made while material is being removed
- Components of setup:
 - tool changes and tool calibration
 - clamping part
 - aligning part






AUTOMATIC TOOL CHANGING





FIXTURING



JIGS



AUTOMATIC SCREW MACHINES



AUTOMATIC SCREW MACHINE

